


## DRIVER DISC content

Layer 1	
\API Package	Folder
\DRIVER	Folder
\USER MANUAL	Folder
README	PDF file



Layer 2 \API Package folder	
\DEMO PROJECT folder	NOT
\Prox API Standard folder	NOT
\Document folder	NOT

Layer 2 \DRIVER folder									
\Flash BIOS folder	BIOS updating tool								
\Platform folder	<p>Driver</p> <ol style="list-style-type: none"> <li>The sequence of setup is, Main Chip =&gt; Intel(R) ME Package =&gt; Graphics =&gt; LAN Chip =&gt; Sound Codec =&gt; Hotfix</li> <li>You will be prompted to reboot when installation is complete.</li> <li>Kaby Lake CPU only win10/64bit</li> </ol> <p><b>Main Chip /Intel® Skylake CPU</b></p> <table border="1"> <thead> <tr> <th colspan="3">Main board version</th> </tr> </thead> <tbody> <tr> <td rowspan="2">Windows 10 IOT Enterprise</td> <td>32bit</td> <td>10.1.1.38</td> </tr> <tr> <td>64bit</td> <td>10.1.1.38</td> </tr> </tbody> </table>	Main board version			Windows 10 IOT Enterprise	32bit	10.1.1.38	64bit	10.1.1.38
Main board version									
Windows 10 IOT Enterprise	32bit	10.1.1.38							
	64bit	10.1.1.38							

\\Platform folder

### Intel® ME Package

Windows 10 IOT Enterprise	32bit	11.6.26.1246
	64bit	11.6.26.1246

### Hotfix

Main board version		
Windows 10 IOT Enterprise	32bit	1.windows10.0-kb 3211320-x86
		2.windows10.0-kb 3213986-x86
	64bit	1.windows10.0-kb 3211320-x64_2ab c94fceb4d1cdd90 8b3bdba473e28e 0c061a3d
		2.windows10.0-kb 3213986-x64_a1f 5adacc28b56d77 28c92e318d6596 d9072aec4

### Graphics /Intel®HD

Main board version		
Windows 10 IOT Enterprise	32bit	15.45.17.4639
	64bit	15.45.17.64.4639

### LAN Chip/ INTEL i219

Main board version		
Windows 10 IOT Enterprise	32bit	21.1.30.0
	64bit	21.1.30.0

### Sound Codec / Realtek ALC888S- Sound Codes\_2.81

Main board version		
Windows 10 IOT Enterprise	32bit	6.0.1.8036
	64bit	6.0.1.8036

\Device folder

**Touch Controller /M172H19-D01.1(Touch)**

Main board version		RA	
Windows 10 IOT Enterprise	Projected Capacitive (Panel: G170EG01 V1)	32/64bit	Driver: 5.14.60.17724 -Release-180724 Custom Edition
			FW: PCAP3188UR_2966_v00_T3_0000 _C000_Mildex_UR_DThqa-E1.3188UR

**Barcode Scanner /**

**RIOTEC-FS5022J /USB Serial**

Windows 10 IOT Enterprise	32bit	1.10.0
	64bit	1.10.0

**IC Card Reader /**

**SKH301-1000C\_ CIDTestAP /USB**

Windows 10 IOT Enterprise	32bit	7.03.0000
	64bit	7.03.0000

**SKH301-1000C\_ Citizen DigatalCertificate /USB**

Windows 10 IOT Enterprise	32bit	3.0.3.21277
	64bit	3.0.3.21277

**RFID Reader /**

**TS-2000\_API-dongleTest /RS232**

Windows 10 IOT Enterprise	32bit	FW-7.02R01/driver-1.0.0.1
	64bit	NA

**Thermal Printer /**

**EPSON-T70II /USB**

Windows 10 IOT Enterprise	32bit	5.07.0.0
	64bit	5.07.0.0

**Layer 2 \USER MANUAL folder**

User Manual	System Guide
PDF File reader	AdbeRdr930_en_US.exe